

DENSO



CAUTION!

When replacing an injector, marked with a compensation code, IT IS NECESSARY TO REGISTER THE ID CODE printed on the upper part of the injector with a genuine OEM - or DENSO diagnostic tool.

When replacing a fuel pump, it is necessary to consult with a genuine OEM - or DENSO diagnostic tool, if IT IS NECESSARY TO RESET THE FUEL PUMP LEARNING VALUE.



DENSO EUROPE B.V.

Hogeweyselaan 165 | 1382 JL Weesp | The Netherlands

Tel. +31 (0)294 - 493 493 | Fax. +31 (0)294 - 417 122

www.denso-am.eu

Driven by
Quality