

# Ignition Coil Puller (Light Duty Scraper Tool)

Art. Nr: PT5344



## Features

- Used for removing “pencil-type” ignition coil on 1.0L / 1.0L TSI / TFSI - 1.2L TSI - 1.4L TSI / TFSI - 2.0L GTI engines.
- Suitable for engine codes (petrol) :  
CJZB, CJZA, CBZB, CJZD, CYVB, CTHD, CTHA, CZCA, CZDB, CZDA, CMBA, CPVB, CPVA, CPCB, CHPA, CPTA, CAXA, CAVA, CAPB, CAVD, CXSA, CDGA, CXEA, CXSB, CKMA, CAVE, CHHB, CHHA, CCZB, CPGA, CHZB, CHYB, CHYA.

|       |                                                                                                                     |
|-------|---------------------------------------------------------------------------------------------------------------------|
| VW    | Up 2011~, Polo 2012~, Golf 2013~, Beetle 2014~, Caddy 2015~, Passat 2014~, Tiguan 2015~, Touran 2015~, Sharan 2015~ |
| Audi  | A1 2012~, A3 2013~                                                                                                  |
| Škoda | Citigo 2011~, Fabia 2014~, Octavia 2013~                                                                            |
| SEAT  | Mii 2011~, Ibiza 2013~, Leon 2013~                                                                                  |

